


**Township Roads – Pavement Condition Rating (PCR)**

**Road Name:** MILLER DR  
**Inspector:** Jim Branch  
**Date:** Apr 7, 2018  
**Last Maintenance Date:** 2005  
**Last Maintenance Type:** Paving



100-90	Very Good
89-75	Good
74-65	Fair
64-55	Fair to Poor
54-40	Poor
39-0	Very Poor

Distress Type	Distress Weight	Severity	Frequency	Deduct Points
Raveling:	10	None - 0	None - 0	
Bleeding:	5	None - 0	None - 0	
Patching:	5	None - 0	None - 0	
Debonding / Potholes:	5	None - 0	None - 0	
Rutting:	10	None - 0	None - 0	
Map Cracking:	5	Medium - 0.6	Occassional - 0.4	1.2
Base Failure:	10	None - 0	None - 0	
Settlements:	5	None - 0	None - 0	
Transverse Cracks:	10	None - 0	None - 0	
Wheel Track Cracking:	15	None - 0	None - 0	
Longitudinal Cracking:	5	Low - 0.2	Occassional - 0.4	0.4
Edge Cracking:	5	Medium - 0.7	Frequent - 0.7	2.45
Pressure Damage Upheaval:	5	None - 0	None - 0	
Crack Sealing Deficiency:	5	None - 0	None - 0	
<b>Total Deduct Points:</b>				4.05
<b>Total Structural Deduct Points:</b>				2.85
<b>PCR:</b>				<b>95.95</b>

**Notes:**

**Photo Documentation**

**Distress Type:** Edge Cracking



-----

**Photo Documentation**

**Distress Type:** Longitudinal Cracking



-----

## Photo Documentation

**Distress Type:** Map Cracking



-----